

NOTES:

Т

\	DIM B		WEIGHT EMPTY		TRANSFER AREA	
nm	in	mm	lb	kg	f†²	m²
603	18.13	461	4.60	2.09	2.93	0.27
476	13.13	334	3.80	1.72	2.18	0.20
349	8.13	207	3.10	1.41	1.43	0.13
349	8.13	207	3.10	1.41	1.78	0.17
476	13.13	334	3.80	1.72	2.71	0.25
603	18.13	461	4.60	2.09	3.65	0.34
730	23.13	588	5.47	2.48	3.68	0.34
857	28.13	715	6.25	2.83	4.43	0.41
730	23.13	588	5.47	2.48	4.58	0.43
857	28.13	715	6.25	2.83	5.21	0.48